

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- ✓ • TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



### INSERT TOWER PERSPECTIVE VIEW

# FIG. 1A

100

## TOWER SIDE VIEW






FIG. 1B

200

DELIVERY SECTION SIDE VIEW




**FIG. 2**




**FIG. 3**

ROLLER AND AIR JET ASSEMBLY



**FIG. 4A**

ROLLER AND AIR JET ASSEMBLY



**FIG. 4A**





FIG. 4B

AIR JET FUNCTION


AIR JET ASSEMBLY SIDE VIEW



**FIG. 5**


160

INSERT HOPPER SIDE VIEW




**FIG. 6**

INSERT HOPPER TOP VIEW




**FIG. 7**

### INSERT HOPPER BOTTOM VIEW



**FIG. 8**



INSERT HOPPER FRONT VIEW



**FIG. 9**


**FIG. 10A**

1000  
HOPPER ADJUSTMENT ASSEMBLY  
SIDE VIEW




HOPPER ADJUSTMENT ASSEMBLY  
TOP VIEW

**FIG. 10B**




**FIG. 11** TOWER WITH HOPPER ADJUSTMENT ASSEMBLY

SENSORS SIDE VIEW




**FIG. 12**


SENSOR MECHANISMS




**FIG. 13**



**FIG. 14**



**FIG. 15**



**FIG. 16**




Fig. 17

Fig. 18





Fig. 19






Fig. 20

Fig. 21





Fig. 22






Fig. 23




Fig. 24